

# Download Briggs And Stratton 17hp Ohv Repair Manual

Hello,First your torque should be around 12 to 15 ft lbs or 140 to 160 inch lbs depending on which wrench you have.when there is gas present in the muffler it usually the float sticking and gas running down intake into the crankcase.the gas will sit on top of the oil and flood the cylinder making go out the muffler.Pull the carb bowl and clean,drain oil and let air out.Replace oil filter and ...DR factory direct sale on brush mowers. 16.5 Briggs and Stratton engine. Strong DR ATV-towable brush hogs mow fields/trails with 44in. cut. 6 mo. trial. 2 yr warranty.I bought one of these machines and it is really great quality and does the job I'm only rating lower because once I received mine and got it home I noticed they didn't send any hardware or a manual with mine.Rover 46 Inch Ride On Mower With 22Hp Kohler 7000 Series V-Twin Ohv Engine: Rover Micro Rider Lawn Mower 24 Inch Cut With Rear Engine 190Cc Briggs & Stratton Ohv And 6 Speed Transmission